

Audi A6

Fitting Locations

No. 802 / 43

Fuses on onboard supply control unit -J519-

Position of fuses, fuse holder

- 1 - Vacant
- 2 - Window regulator single fuse 2 - S280- (30A)
 - up to October 2005
- 2 - Heater element fuse 1 -S276- (40 A)
 - from June 2007
- 3 - Driver seat adjustment thermal fuse 1 -S44- (30A), driver seat adjustment fuse 1 -S44- (only lumbar support 10A)
 - is dropped, from model year 2007
 - for models from model year 2007 → [page 802/42](#)
- 4 - Window regulator single fuse - S37- (30A)
 - up to October 2005
- 5 - Heater element fuse 2 -S277- (50 A)
 - from June 2007

